


Appendix D: Audit Findings

Legend

- access
- connectivity
- crossing deficiency
- infrastructure condition
- obstruction
- safety issue
- missing footpath
- narrow footpath
- Inner West Suburbs
- Inner West LGA



© OpenStreetMap (and) contributors, CC-BY-SA, Esri, HERE, Garmin, USGS, METI/NASA



Gold Coast
Suite 26, 58 Riverwalk Avenue
Robina QLD 4226
P: (07) 5562-5377
W: www.bitziosconsulting.com.au

Brisbane
Level 2, 428 Upper Edward Street
Spring Hill QLD 4000
P: (07) 3831-4442
E: admin@bitziosconsulting.com.au

Sydney
Studio 203, 3 Gladstone Street
Newtown NSW 2042
P: (02) 9557-6202

Title: Inner West PAMP Audit Issues	Project Number:	P4909
	Date:	05/08/2021
	Issue:	2